

Annexure D

BUILDING SAFETY CERTIFICATE

Dated: ... 19/08/2025

No.

It is certified that the existing building **Kranti Shikshan Sanstha Virali (BK), At Post- Kondha**

Kosra, Tah- Pauni, Dist- Bhandara

is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground floor + first + second floor					

The building is owned/occupied by **Mother Teresa Public School Kondha Kosra, Tah- Pauni, Dist- Bhandara** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Public Works Department** (Name of Department/Govt.) on **19/08/2025** (date of inspection) in the presence of **Shri. Kashiram Badgujar Humane** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **20/08/2025** for a period of **2 (Two)** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. NA

2. NA

3. NA

4. NA

Issued on **20/08/2025** at **Kondha/Kosra** by

*Strikeout whichever is not applicable. Incase of block is more than six use separate sheet for detail.

Signature with Seal

Name :

Designation :

Name & Address of Department/ Office: _____

ग्रामपंचायत कोंडा
ता. पवनी, जि. भंडारा