



जावक क्र. :-

दिनांक:- 1918/2025

## **Annexure C**

## PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITIONCERTIFICATE

No.

Dated:

It is certified that an inspection team headed by...Mr. Sunil Pakhmode, Village Development Officer (Name of Officers with designation) from Grampanchayat Kondha PHED inspected the Mother Teresa Public School Kondha Kosra, Tah-Pauni, Dist-Bhandara (Name & Address of the school) on 12/07/2025 (date of inspection) and on the basis of Water Test Report (Attached) bearing no 417 dated...02/07/2025 of Sub district Water Testing Laboratory Pauni (PHED Lab) certified that the Mother Teresa Public School Kondha Kosra, Tah-Pauni, Dist-Bhandara (Name of school) has safe drinking water facilities for the students and members of staff of the institution. School is also maintains the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/ State/ U.T. Govt.

This certificate is valid till 31/03/2026

Signature with Seal:

Name

Mr. Sunil Pakhmode

Designation : Village Development Officer

Name & Address of the Office/ Department :

Grampanchayat Office Kondha,

Tah- Pauni, Dist- Bhandara

To
Mother Teresa Public School
Kondha, Kosra, Tah- Pauni, DistBhandara (Name & Address of the
Institution)

Note: The certificate is to be issued by authorized officer/PHED Lab/local bodies